



Adaptor kit-K: to adapt Kinman solder cables pickups to plug-in harness connection.

NOTE: Use LEAD solder.



Adaptor kit-O: to adapt regular solder cables pickups to plug-in harness connection.

NOTE: Use LEAD solder.



NOTE: I recommend you don't shrink the insulating tubes until you know the phase of the other pickup is compatible with the Kinman's. You might have to reverse the connection of the other pickup to get in-phase sounds in combination positions 2 & 4. Once phase is correct then shrink the insulating tubes of the adaptor kit.